This STANDARD is not met as evidenced by: Based on observation it was determined the fa cility falled to maintain the Fire Alarm system.

requirements of NFPA 70 and 72.

The findings included:

Orn 12/9/13 at 2:40 PM, observation within the ce iling area of the main hall revealed an ov erloaded junction box with too many electrical wires.

Theis finding was acknowledged by the Ad ministrator and verified by the Maintenance Director during the exit on 12/9/13, NFPA 101 LIFE SAFETY CODE STANDARD

K 067 SS=E

Heating, ventilating, and air conditioning comply with the provisions of section 9.2 and are installed in accordance with the manufacturer's specifications. 19.5.2.1, 9.2, NFPA 90A, 19_5.22

K 067

K-067 NFPA 101 Life Safety Code Standards (Corrected on 12/10/13)

The Exhaust fan for the men's and women's locker room was not working. Fan motor had failed in between monthly inspections. Maintenance has replaced the fan motor on 12/10/13. Maintenance will continue to conduct monthly exhaust fan checks. Extra motors and fan belts are on site to repair exhaust system failures.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVES SIGNATURE

TITLE

(X6) DATE

1/1/14

Any deficiency statement ending with an asterisk (") denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are discloseble 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the determined decuments are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

KINDRED NURSING AND REHABILITATION-MASTERS SUMMARY STATEMENT OF DEPICIENCES BY FILL PROVIDERS ILLAY OF CORRECTION RECOULT ON INCIDENCY MUST BE PRECEDED BY FILL PROVIDERS ILLAY OF CORRECTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE OF CONTINUED FROM SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE OF CONTINUED FROM SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE OF THE AP	NAME OF	PROVIDER OR SUPPLIER	445136	B. WING		4-10-
PREFIX REGULATORY OR LSO IDENTIFYING INFORMATION) K 057 Continued From page 1 This STANDARD is not met as evidenced by: Based on testing and observation, it was not working. The finding was acknowledged by the Administrator and verified by the exit Interview on 12/9/13. K 147 This STANDARD is not met as evidenced by: Based on testing and observation, it was not working. The finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit Interview on 12/9/13. NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 K 147 Con 12/9/13 at 2:20 PM observation within the celling area above G-Hall fire doors revealed two junction boxes with missing covers. This finding was acknowledged, corrected and verified by the Maintenance Director during the exit interview on 12/9/13.	I .		ABILITATION-MASTERS	. [12/09/
This STANDARD is not met as evidenced by: Based on testing and observation, it was determined the facility failed to maintain the Heating, Ventilation and the Air-conditioning system. The finding included: On 12/9/13 at 10:45 AM testing of the exhaust fan unit within the men's locker room revealed the Unit was not working. This finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 12/9/13. The finding and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 This sTANDARD is not met as evidenced by: Based on observation, it was determined the facility failed to maintain electrical equipment. On 12/9/13 at 2:20 PM observation within the ceiling area above 'G'-Half fire doors revealed two junction boxes without any cover plates. This finding was acknowledged, corrected and verified by the Maintenance Director during the exit Interview on 12/9/13.	PREFIX (EACH DEFICIENCY)			PREFIX	PROVIDER'S PLAN OF CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRO	
determined the facility failed to maintain the Heating, Ventilation and the Air-conditioning system. The finding included: On 12/9/13 at 10:45 AM testing of the exhaust fan unit within the men's locker room revealed the unit was not working. This finding was acknowledged by the Administrator and ventiled by the Maintenance Director during the exit interview on 12/9/13. NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 This STANDARD is not met as evidenced by: Based on observation, it was determined the facility failed to maintain electrical equipment. On 12/9/13 at 2:20 PM observation within the ceiling area above 'G'-Hall fire doors revealed two junction boxes without any cover plates. This finding was acknowledged, corrected and verified by the Maintenance Director during the exic Interview on 12/9/13.	K 067	Continued From page	≥ 1	K 067	7	
:MS-2587(Q2-99) Provious Observa	K 147 N E W T E fa Oce jui The	determined the facility Heating, Ventilation as system. The finding included: On 12/9/13 at 10:45 A unit within the men's in unit was not working. This finding was acknow Administrator and veriff Di rector during the exit NEPA 101 LIFE SAFET Electrical wiring and equith NEPA 70, National with NEPA 70, National collity failed to maintain on 12/9/13 at 2:20 PM of citing area above 'G'-Ha on ction boxes without an is finding was acknow criffed by the Maintenan	observation, it was failed to maintain the aid the Air-conditioning. If testing of the exhaust fancker room revealed the wledged by the ed by the Maintenance interview on 12/9/13. Y CODE STANDARD Ilipment is in accordance Electrical Code. 9.1.2 The servation within the electrical equipment. It was determined the electrical equipment. It was determined the electrical equipment.	K 147	There were two junction boxes that did not covers on them. This was corrected by maintenance before the inspector finished linspection. Maintenance has extra cover for junction boxes on site in the event of finding	have lis
	MS-2507(Q2	(-99) Provious Versions Obseriors	Event ID: PUZBZ1			

Sylvia J. Buston

12/3/13